

Oil Field Environmental Incident Summary

Incident: 20160718120242 **Date/Time of Notice:** 07/18/2016 12:02

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: ARLEY 21X-18A

Field Name: GRINNELL

Well File #: 26065

Date Incident: 7/17/2016

Time Incident: 05:00

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 96

Sec: 18

Qtr:

Location Description:

Submitted By: Shawn Dahl

Received By:

Contact Person: Shawn Dahl
2732 Hwy 85 North
Alexander, ND 58831

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units
Oil	2	Gallons

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/29/2016

Clean Up Concluded: 7/22/2016

Risk Evaluation:

None

Areal Extent:

2' X 5' area affected off location.

Potential Environmental Impacts:

None

Action Taken or Planned:

They shut the flare in and diverted fluids and gas to the tanks. Per landowner, no cleanup activities initiated.

Wastes Disposal Location: N/A

Agencies Involved:

Updates

Date: 7/18/2016 **Status:** Inspection

Author: Kangas, Kathleen

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site at 5:20 p.m. 84 degrees F, sunny, wind 9 mph SE. On-site personnel pointed to an area south of the flare. Some slight impact seen on the wellpad. No impact initially noticed off well pad. Some slight misting of oil may have landed off site, but none was seen in visual survey. Impact is SW of corner of flare. Per submitted report, landowner has requested no cleanup activities. Follow-up with landowner recommended.

Date: 7/19/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted areas off location. Follow-up is required.

Date: 8/1/2016 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 5:02 p.m. Weather was partly cloudy with wind out of the SW at 5 mph and temperature of 81 degrees F. There was a workover rig located on the pad, and work was occurring on site. Will have to do follow-up after the rig leaves the site. In addition, the landowner has requested no cleanup activities of the area. Follow-up with the landowner recommended.